



Product Support Bulletin N° PSB005
10th October 1997

Adventure Series Software Release Overview

Introduction

The new software for the Adventure Series of products covers the following consoles;

Console	New Software Version N°
• Navigator	V4.1
• Navigator EPX	V4.1
• Pathfinder	V2.2
• Pathfinder EPX	V2.2
• Explorer	V1.2
• Explorer EPX	V1.2

The software updates do not introduce any new features but resolve a number of problems which have been reported over the last few months.

This document lists the performance issues addressed and details ordering information.

Maintenance Issues

The following reported problems have been fixed:

Navigator

- ☞ Cue 1 is no longer lost after loading data into a 'clear' console.*
- ☞ Cues with focuses no longer occasionally fade with incorrect speed.*

Pathfinder

- ☞ Channel data for some Sequences or Cues is not lost on power-up.*
- ☞ Possible data corruption of Cues and Sequence steps no longer occurs after clearing.*
- ☞ The Set button no longer decrements LTP channels on each press.*
- ☞ Occasional triggering of Cues on fader down no longer occurs.*

Explorer

- ☞ Channel 1 flash button no longer flickers channel when held down.*
- ☞ The Set button no longer decrements LTP channels on each press.*
- ☞ Occasional triggering of Cues on fader down no longer occurs.*

Availability

These software releases will be available from 10th October 1997 and can be ordered on EPROM as follows:

- **All EPROM's are supplied at a net price of £25 each**
- To ensure that you receive the correct upgrade please include the following information with your order:
 - ✎ ESC2296/EPROM Navigator Software V4.1
 - ✎ ESC2796/EPROM Navigator EPX Software V4.1
 - ✎ Ⓢ ESC2297/EPROM Pathfinder Software V2.2
 - ✎ Ⓢ ESC2797/EPROM Pathfinder EPX Software V2.2
 - ✎ ESC2700/EPROM Explorer Software V1.2
 - ✎ ESC2710/EPROM Explorer EPX Software V1.2

Ⓢ Pathfinder

To ensure that you receive the correct software for your Pathfinder upgrade you need to inform Celco whether you have a first or second generation Pathfinder. In the first generation Pathfinder the faders of Preset 1 and 2 are arranged in one continuous bank. In the second (*current*) generation of Pathfinder the faders of Preset 1 and 2 are arranged in two blocks with a gap between faders 12 and 13.

CREDIT CARD HOTLINE

Really speed things up by using our new credit card telephone ordering system and calling Celco Sales Support on +44 (0) 1322 282 218. We will have your Upgrade on its way in under 24 hours.

For your own security do not send your credit card details across the Internet.