

## **PSB N°015 Y2K Statement**



### **Year 2000 Compliance**

**The following products and their derivatives are year 2000 compliant:**

#### **Consoles:**

- CL3100 Ventura 2
- CL3100/2xHUD Ventura 2 Twin HUD
- CL2296 Navigator
- CL2796 Navigator EPX
- CL2297 Pathfinder
- CL2797 Pathfinder EPX
- CL2700 Explorer
- CL2710 Explorer 2 and Explorer EPX
- Celco Series 2 Range
- Celco 88 Range
- Aviator Range

#### **Dimmers:**

- CL2525 Fusion Wall Mount
- CL2526 Fusion 1210 Rack Mount
- CL2527 Fusion 1216 Rack Mount
- CL2528 Fusion 1220 Rack Mount
- CL2524 Fusion 0632 Rack Mount
- Celco Series 2 Dimming Range

#### **Accessories:**

- CLFUS151 Fusion DMX Splitter 1.5.1
- CLFUS152 Fusion DMX Splitter 1.5.2
- CL2259-1 Fusion DMXdtr

Year 2000 conformity shall mean that neither performance nor functionality is affected by dates prior to, during and after the year 2000.

Certain variants of the consoles run a third party operating system known as "General Software Embedded DOS" which includes time and date functions. All Celco products that use this operating system exclude the use of these functions.

Celco Limited  
Midas House  
Willow Way  
London  
SE26 4QP  
England

web: [www.celco.co.uk](http://www.celco.co.uk)

tel: +44 (0) 20 8699 6788

fax: +44 (0) 20 8699 5056

email: [sales@celco.co.uk](mailto:sales@celco.co.uk)

Celco Products are manufactured in the European Union.

In a policy of continuous improvement, Celco Limited reserve the right to change features, specifications and prices without notice.

Ventura, Explorer and Fusion ® are registered trademarks of Celco Limited.

Copyright © Celco Limited, 1981 – 1999.

All Rights Reserved.

